

दिल्ली सरकार

आप की सरकार

# RWH ADEQUACY CERTIFICATE



This is awarded to Geeta Bal Bharti School,  
regarding adequacy and functionality for RWH structure at Rajgarh Colony, Delhi - 110031

Referring to your letter dated 18-10-2024, in which you have informed that Rain Water Harvesting has been installed at your said premise. The rain water harvesting structure was inspected by NGT/DJB inspection team on dated 26-10-2024 and found sufficient and adequate to harvest the catchment area of your premises. This certificate is issued based on the above joint inspection report and same is valid for two years subject to terms and conditions as under:

1. RWH system maintained neat and clean at every time for proper recharge of rain water.
2. Owner may allow for inspection of RWH by any NGT/DJB and other inspection teams for inspection and also facilitate for the same.
3. In case, if any dispute/litigation on the premises for which above certificate issued, the above certificate will be treated as cancelled.
4. In case, owners make changes in above RWH system, he may intimate to this office.

No./Year 408/2024

Date of Issue 29-10-2024

Executive Engineer (RWH/DWC)

Delhi Jal Board, Room No. 208, Executive Engineer, RWH/Delhi  
Contact No. 011-23558264 E-mail: rainwaterharvesting2013@gmail.com  
Varunatalaya Ph-1, New Delhi-110005